Work Order Monday, August 3	r ID 61623 20, 2010 2:24:57 PM											Page 1
Revision ID: Item Name: B	0500-572-011 Bearpaw			Accept					Setup	Start Stop		
Start Date: 8 Required Date: 9 Reference:	/30/2010 Start Qty /6/2010 Req'd Qt		1 1841 A 1141 A 1841 1 1841 A 1141 A 1841		Cust Item 1 Customer:	D:	_		_	C 4 4	1 1 88 111 81 88	11 2 121 1121 1221
	Process Plan:	/ (Date: <u>//></u> F-3.	Tooling: SPC (Y/N):		ate: ate:			Run	Start Stop		
Sequence ID/ Work Center ID	Operation Description			Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr D2435	Revision Nbr	Ø		0.00							Pto	→
DC Document Control		VT CONTROL Memo Photocopy blues	ile and create labels per	0.00 PPP D500-572-011	CHG005 COL	حاله						
160 Packaging Packaging	Pick Kit	Мето		0.00				-6	040	D. f.14	15	2
170 QC Quality Control		Inspect kits for	completeness	0.00	Diololiz	_			2			

*

3 ,

W/O: 61	623	WORK ORDER CHANGES			-	· · · · · · · · · · · · · · · · · · ·	
DATE	STEP	Pern. Jany. PROCEDURE CHANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
iopolis	女 100	up Date leaser by to have the correct enformation	Be	100 W. 1/3			10/10/12

Part No:D500-572-011 PAR #:	_ Fault Category:	NCR: Yes No DQA:	Date:
Resolution:	Disposition:	QA: N/C Closed:	Date:

NCR:			WORK ORD	ER NON-CONFORMANC	E (NCR)				
		Description of NC	Description of NC Corrective Action Section B						
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Verification Section C	Approval Chief Eng	Approval QC Inspector	
·									

Work Order ID 61623

Monday, August 30, 2010 2:24:57 PM



Page 2

Item ID:

D500-572-011

Accept



Setup Start

Stop



Revision ID:

Item Name:

Bearpaw

Start Date: 8/30/2010 Required Date: 9/6/2010

Start Qty: 2.00

Req'd Qty: 2.00



Cust Item ID:

Customer:

Reference:

Approvals:

QC:

Process Plan:

Date:

Date:

Tooling: SPC (Y/N):

Date: Date: Run

Start



Set Up/

Run Hours 0.00

Tool ID

Tool # Plan Code

Accept Qty

Reject Reject Qty

Stop

Insp. Number

Stamp

180

Sequence ID/

Work Center ID

Packaging

Packaging

Packaging

Operation

Description

Identify and pack for shipping as per PPPD500-572-

011□Location:

Memo

Memo

190

Quality Control

QC21- Final Inspection - Work Order Release

0.00

0.00

50/10/13/75 MX 10-13

W/O:			WC	ORK ORDER CHANG	ES				
DATE	STEP	PRC	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspectos
							:		
						:		; ;	
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA :		Date: _	
	R	esolution:	Dispositio	n:	_ QA: N/C CI	osed:		Date: _	
NCR:		`	WORK ORD	ER NON-CONFORM	ANCE (NCR)			
DATE	STEP	Description of NC	Initial		ion B Sign &	Verificat		Approval	Approval
		Section A	Chief Eng	Action Description Chief Eng	Date	Section	<u>С</u>	Chief Eng	QC Inspector
	,								
								t	
									!

Picklist Print

Monday, August 30, 2010 2:25:01 PM

Work Order ID: 61623

Parent Item:

D500-572-011

Parent Item Name: Bearpaw



Start Date: 8/30/2010

Required Date: 9/6/2010

Start Qty: 2.00

Required Qty: 2.00

Comments:

IPP Rev:C□04.02.17□Blank size changed□KJ/JLM□

IPP Rev:D 07-01-02 IPP Rev:E 08-01-09

Was K10007 Added Step 2

JLM JLM

Verified By:EC

Component Item ID/ tem Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Status Issued
QS200-M44Ş 		Purchased	No			120	Each	32.0000	2	4 ~		a
				<u>Location</u>	<u>1</u>	Loc	<u>Oty</u>	Loc Code				
				ST450	114917 115410	v ·	32 12 20		<u> </u>	1/149/	7	a
N4-15A 		Purchased	No			170	Each	387.0000	8	16 M/100°	5/48	4× 6
				<u>Location</u>	<u>1</u>	Loc	<u>Oty</u>	Loc Code				_
				ST338			112					
				ST358			275					
					112905		12		<u> </u>	1/12905	してで	
					114784		21		_			
					115108		142					
					115371		100		_			

NAS1149D0463J Purchased

No

170 Each

0.0000

Washer

W/O:			W	ORK ORDER CHANG	GES				• \
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspectors
Part No	•	PAR #:	Fault Cat	egory:	NCR: Ye	es No I	DQA:	Date: _	· · · · · · · · · · · · · · · · · · ·
	Re	solution:	Dispositi	on:	QA: N/C	Closed:		Date: _	
NCR:		•	WORK ORE	DER NON-CONFORM	ANCE (N	CR)			
DATE	STEP	Description of NC Section A	Initial	Corrective Action Sec Action Description	etion B		rification Section C	Approval Chief Eng	Approval QC Inspector
~ .~		Section A	Chief Eng	Chief Eng	Da		Section C	Office Erig	QO IIISPECIOI
								:	i
,									
								÷	
							•		

Monday, August 30, 2010 2:25:01 PM

Work Order ID: 61623 Parent Item: D500-572-011 Parent Item Name: Bearpaw D2182B



Start Date: 8/30/2010

Required Date: 9/6/2010

Start Qty: 2.00

Required Qty: 2.00

217.6285

1.666

3.332

Rubber Cushion

(D2182B050) cut 4 at 5.00"

D2274 Sadius Block

Manufactured No

Manufactured

Manufactured

Manufactured

No

No

No

Location Loc Qty ST402A 28.57 30872 13.67 39986 12.4 45405 2.5 ST410 189.05854 52649 189.05854

170

170 Each 180.0000

Loc Code

234.0000

Loc Code

5108

Clamp

Location Loc Qty ST010 180 51427 12 59108 168 170 Each

170 Each 0.0000

Location Loc Oty Loc Code ST456 234 52645 6 59123 28 60852 200

	. Johado					*			••
W/O:			WO	RK ORDER CHANG	ES	_			
DATE	STEP	PRO	OCEDURE CHAP	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
		4							
					:				
Part No):	PAR #:	Fault Cated	norv:	NCR: Yes	No DO	Δ-	Date:	
		esolution:							
NCR:			WORK ORDE	ER NON-CONFORMA	NCE (NCF	₹)			
DATE	OTED.	Description of NC		Corrective Action Section		Verific	cation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	& Sect	ion C	Chief Eng	QC Inspector
			;						

Picklist Print

Monday, August 30, 2010 2:25:01 PM

Page 3

Work Order ID: 61623

Parent Item:

D500-572-011

Parent Item Name: Bearpaw



51406

58568

Location

ST017

No

Start Date: 8/30/2010

Required Date: 9/6/2010

Start Qty: 2.00

Required Qty: 2.00



5 Washer

D2529

MS21042L4

Manufactured No

Purchased

Loc Qty

170

178 12 166 170 Each

Each

Loc Code

2,535.000

Loc Code

178.0000

Location	Loc Qty
ST300	2535
112314	12
113422	68
114523	28
114718	16
114784	491
115108	1920

Dari Ae	ospace	# LIU							٠, ٠,
W/O:			WO	RK ORDER CHANGES	3				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector •
Part No):	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A:	Date: _	
	R	tesolution:						Date: _	
NCR:		1	WORK ORDE	ER NON-CONFORMAN	ICE (NCF	₹)			
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Section Action Description Chief Eng	B Sign 8	k Sect	cation tion C	Approval Chief Eng	Approval QC Inspector
			Office Ling	Office Ling					
			,					į	
	•			·					

ICA Page 29 (30 blank) of 30

REFERENCE ONLY

32.3 WEIGHT AND BALANCE

1 - 4 - 11 - 41 - 12	Nava i mb4	LAT	ERAL	LONG	ITUDINAL
Installation	Weight	Arm	Moment	Arm	Moment
D500-572-011 Bearpaw Installation	8.5 lb	0.0 in	0.0 lb-kg	130 in	1105 in-lb
	3.86 kg	0.0 m	0.0 m-kg	3.30 m	12.74 m-kg
D500-572-021 Narrow Bearpaw Installation	7.5 lb	0.0 in	0.0 lb-kg	130 in	975 in-lb
	3.41 kg	0.0 m	0.0 m-kg	3.30 m	11.25 m-kg
D500-572-013 Bearpaw Installation	11.4 lb	0.0 in	0.0 lb-kg	128 in	1459 in-lb
	5.17 kg	0.0 m	0.0 m-kg	3.25 m	16.80 m-kg
D600-572-015 Bearpaw Installation	11.4 lb	0.0 in	0.0 lb-kg	122 in	1391 in-lb
	5.17 kg	0.0 m	0.0 m-kg	3.10 m	16.03 m-kg

32.4 PARTS LIST

Qty D500 -572 -011	Qty D500 -572 -021	Qty D500 -572 -013	Qty D600 -572 -015	Part Number	Description
Υ.''				D500-572-011	BEARPAW INSTALLATION
3	Х			D500-572-021	NARROW BEARPAW INSTALLATION
		Х		D500-572-013	BEARPAW INSTALLATION
			Х	D600-572-015	BEARPAW INSTALLATION
2				D2435 /	BEARPAW
	2			D2671	BEARPAW
		2		D2995	BEARPAW
			2	D2996	BEARPAW
4	4	4		D2182B050 >	RUBBER CUSHION
			4	D2182B060 7	RUBBER CUSHION
8	8	8	8	D2274 /	RADIUS BLOCK
4	4	4		D2438 //	CLAMP
			4	D2519	CLAMP
8	8	8	8	D2529 7	WASHER
-					
		8	8	AN4-1 <u>3</u> A	BOLT
. 8	8			AN4-15A/	BOLT
8	8	8	8	AN960JD416 15	WASHER
8	8	8	8	MS21042L4 -	NUT (OR MS21042-4)
2	2			QS200M44S	CLAMP
			4	QS100M24S	CLAMP

• COPYRIGHT © 2001 BY DART AEROSPACE LTD •
THIS DOCUMENT IS PRIVATE AND CONFIDENTIAL AND IS SUPPLIED ON THE EXPRESS CONDITION THAT IT IS NOT TO BE USED FOR ANY PURPOSE OR COPIED OR COMMUNICATED TO ANY OTHER PERSON WITHOUT WRITTEN PERMISSION FROM DART AEROSPACE LTD.